HEAVY DUTY TOOLS & EQUIPMENT



OT7503 Outer Tie Rod Remover

- Works on FWD and RWD Import and Domestic Vehicles
- Up to 5 Tons of Force can be Applied

USER \$139.35 SRP **\$115.51**

1-Ton Grip-O-Matic Puller

- 3-Jaw, 21/8" Max Reach, 31/4" Max Spread
- 5/16" 24 x 37/8" Screw
- 9/64" Jaw Thickness, 1/4" Width
- Forged from Quality Steel, Heat Treated

SRP \$79.49 USER \$95.88



OT8032A Ford Ball Joint Adapter Set

• Low Profile Design for GM, Ford, & Chrysler Vehicles

• A Required Tool to Fill or Add Fluid to the 5R55W Automatic Transmission used on 2003 - Newer Ford Explorer

SRP **\$26.32**

- Removal & Installation of Lower Ball Joint on 1996 - 2004 Ford Taurus & Mercury Sable Vehicles Lower Ball Joint can now be Replaced without
- having to Replace Entire Spindle Assembly
- Adapters are used with OT7248 C-Frame

OT307-437 (OT6604)

OT6509

Transmission Fluid Fill Adapter

3/8" & 5/16" Fuel Line

USER \$33.19

Disconnect Tool

SRP **S173.56** USER \$209.37



LID QI

OT303-562 (OT6469)

Ford Syncro Positioning Tool

Ford Camshaft Sensor Synchronizer Tool for Servicing: 1996 - 1998 3.8L V6 Mustang, Windstar; 1997 3.8L V6 Thunderbird/Cougar; 1997 - 2002 4.2L V6 Econoline, F-Series Truck: 1996 - 1998 5.0L V8 Ford Explorer. Mercury Mountaineer



OT303-529 (OT6472)

Ford Camshaft Sensor **Synchronizer Tool**

• Works on 1995 - 1997 3.0L, V6 Windstar, Aerostar & Ranger 1996 - 1997 3.0L 2-Valve V6 Ford Taurus & Mercury Sable 1996 - 1998 4.0L V6 Aerostar, Ranger & Explorer

• Used to Synchronize the Camshaft Sensor to the No 1 Cylinder

SRP \$154.04

LTD QTY

OT7677 Exhaust Hanger Pliers

- To remove Rubber Blocks Supporting Exhaust System Hanger Brackets
- Features a 2-Position Slip Joint for use on many Sizes of Hanger Blocks

USER \$430.82

SRP **\$357.12**

OT230582

02 Sensor, Class R-21A

MADE IN U.S.A.

SRP **\$189.75**



LTD QTY

LTD QTY


OT3550 Torque Extensions Kit

SRP **\$27.51**

- Turn your Digital Multimeter & any Standard Square Drive Wrench into a Torque Wrench
- Accuracy within ±3%
- Includes Torque Module, 1/4", 3/8" & 1/2" Torque Extensions, 9V Battery, Manual & Carrying Case

SRP **\$647.37**

Chrysler Fuel Pump Module Spanner Wrench



• For most 1994-2005 Chrysler Vehicles, & 1995-2004 Jeep Vehicles

SRP **5177.67** USER \$225.60

OT216094

Universal Test Lead Set

Hyundai, Diahatsu; Mitsubishi 1985 - 1988; 1989 - 1992

SRP **\$17.37**



LTD QTY

LTD QTY



Wheel Dolly

- 1,500 Capacity Dolly will Remove, Transport & Replace Dual Wheel & Tire Assemblies without Strain or Struggle
- Swivel Casters: 31/2" Front & 3" Rear
- 43" by 42" Floor Space
- Hydraulic Jack Provides over 61/2" of Lift & Tilts Wheel Assembly 7° to Prevent Damage to Wheel Seal
- Includes: 6' Support Chain to Hold Load in Place

USER \$1,274,40

SRP \$1.131.86



